Accessories



VACUUM GAUGE


Vacuum level : 0 to -100Kpa (0 to -76cmHg)

Accuracy : ±1.6% Full scale
Material : Brass, ABS, PMMA

Weight : 60g







PRESSURE GAUGE

Pressure level: 0 to 10bar (0 to 150psi)

Accuracy : ±1.6% Full scale
Material : Brass, ABS, PMMA

Weight : 60g



DG-40A

